	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Erro s
1	BRS	L1	1005		US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/28 13:30	_		
2	BRS	L2	568	134 37 793 CTIC	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/28 13:30			
3	BRS	L3	388	ICL 2 Lann Sint	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/28 13:31			

	Hits	Search Text	DBs	Time Stamp
1	31915	((antenna adj elements) antennas) and (substrate pcb)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
2	4236	L9 and "343"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
3	716	L10 and (slot and patch\$2)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
4	2477	L10 and (feed)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
5	609	L11 and ground	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
6	1962	L12 and ground	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
7	2074	L13 L14	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
8	81	L15 and @py<"1980"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/01/14 14:52
9	2	("6480162").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT: IBM, TDB	2005/01/14 15:22